Monday, 16/03/2009 1:55:26 PM

User:

Linda Lacelle

## **Process Sheet**

Customer

: CC-DAR01 Dart Aerospace Ltd.

Job Number **Estimate Number**  : 46517

: 10804

P.O. Number

: 16/03/2009 This Issue

: NC Prsht Rev.

: 11 First Issue

**Previous Run** 

: 46508

Checked & Approved By

Comment

Written By

: SMALL /MED FAB

S.O. No. :

Type

**Drawing Name** 

**Part Number** 

: SCRAP20

: D2735-1/-3

· SCRAP PARTS

**Drawing Number** 

**Project Number** 

**Drawing Revision** 

Material

: 23/03/2009 **Due Date** 

Qty:

Each 1 Um:

**Additional Product** 

Job Number:



Seq. #:

**Machine Or Operation:** 

Description:

1.0

SMALL FAB 1

SMALL & MEDIUM FAB RESOURCE 1



Comment: SMALL & MEDIUM FAB RESOURCE 1

PULL FROM STOCK:

P/N

D2735-1

B 38455 pty
B 39819 qty

D2735-3

B 39886

D3402-01 D 3405-03

**DESTROY/SCRAP PARTS** 

PER ECN08-588

35779

B 34841 0B41764 D

2.0

D27351

Lug Bracket



Comment: Qty.:

1.0000 Each(s)/Unit Total:

1.0000 Each(s)

Comment: Qty.:

Lug, GHW Adapter

3.0

D27353

Lug Bracket



1.0000 Each(s)/Unit

Total:

1.0000 Each(s)

Lug Bracket

Page 1

Form: rprocess

Date: , User:

Monday, 16/03/2009 1:55:27 PM

Linda Lacelle

**Process Sheet** 

Customer: CC-DAR01 Dart Aerospace Ltd.

**Drawing Name:** D2735-1/-3

Job Number: 46517

Part Number: SCRAP20

Job Number:



Seq. #:

**Machine Or Operation:** 

Description:

4.0

QC21

FINAL INSPECTION/W/O RELEASE



09/03/18

Comment: FINAL INSPECTION/W/O RELEASE

Job Completion



aly. 3/3

W 09-03-18